TOTAL EARTH SERVICES, LLC WITNESS STATEMENT REGARDING ACCIDENT

Date of this report: $1 - 10 - 19$
Date of Accident: 1-10-19
Witness Name: (b) (6)
Occupation: Super Visor
Location of Accident witnessed: Veterans Hospital Gaines Ville, Fla
Describe clearly how the accident occurred and what happened. For all motor vehicle accidents draw a
diagram on the other side:
It there was any ground water. We due
as deep as we could lowered a latter into
the excavation (b) (6) was on the latter
with the grade rod we got a shot he dropped
his hard hat (b) (6)
to leave the pat come up the ladder
he was approximately 43-5 ft down
he handed (b) (6) the gradered (b) (6) turned
to set it down (b) (6) went down the
ladder to retrieve his hard hat the bank
gave wax covering him I don't know
how long before they got to him but he was
breathing he came up the ladder on his own
power he was then transported to Shands
hospital. Under no circumstanes was he
hospital. Under no circumstanes was he supposed to go down that ladder below where
(b) (6) (b) (6) 1-10-19

Printed name of Witness

Signature of Witness/Date

TOTAL EARTH SERVICES, LLC WITNESS STATEMENT REGARDING ACCIDENT

(b) (6)	(b) (6) 1-10-
	e
exploritory,	
he shot that a not intended to	work out of it was just
diagram on the other side:	
Describe clearly how the accident o	occurred and what happened. For all motor vehicle accidents draw a
Occupation:	
Witness Name:	
Date of this report: Date of Accident:	

0032

Printed name of Witness

Signature of Witness/Date